

[fr]Problème[/fr][en]Problem[/en]

Maintenance

Publié par :

Publié le : 26-04-2013 18:10:00

[fr]En terminant la révision semestrielle je tombe sur un petit problème. Il y a une craque (fissure) sur la cloison qui supporte le radiateur d'huile. Cette faiblesse est connue et j'avais essayé de l'anticiper en installant une barre de renfort sur le moteur (voir [ici](#)). Visiblement ça n'a pas été suffisant.

On voit la fissure verticale sur la droite de la photo. [fr][en]As I was about to finish the inspection, I noticed there was a crack on the rear baffle supporting the oil cooler. This problem is known and I had tried to anticipate it by installing a steel brace (see [here](#)). It seems it was not enough. [fr][en]The part is off the engine. The crack is on the smaller side on the right. Now, on to the repair. [fr][en]The part is now repaired, I've added a reinforcing angle. [fr][en]The part is off the engine. The crack is on the smaller side on the right. Now, on to the repair. [fr][en]The crack is the thin vertical line near the nutplate on the right. [fr][en]